



Certificate Number **17-BL3355922-A**  
Effective Date **07-JUL-2017**  
Expiry Date **07-JUL-2020**  
ABS Port Office **BALBOA PORT**  
Specialist's Website **www.seminsa.com.pa**

---

## CERTIFICATE OF Recognized External Specialist

This is to certify that

**Servicios Maritimos e Inspecciones, S.A. (SEMINSA)**

located at

**Colon Maritime Investor Export Processing Zone (347) Central Avenue**

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

### **Fire Extinguishing Systems Inspection/Maintenance**

It is the responsibility of the Service Provider to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's website (noted above). The products and models allowed to be serviced are to be listed on the company's website. The ABS office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors, etc.



Ernesto Guerra, Surveyor



Certificate Number **17-BL3355922-B**  
Effective Date **07-JUL-2017**  
Expiry Date **07-JUL-2020**  
ABS Port Office **BALBOA PORT**  
Specialist's Website **www.seminsa.com.pa**

---

## CERTIFICATE OF Recognized External Specialist

This is to certify that

### **Servicios Maritimos e Inspecciones, S.A. (SEMINSA)**

located at

**Colon Maritime Investor Export Processing Zone (347) Central Avenue**

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

### **Self Contained Breathing Apparatus Maintenance**

It is the responsibility of the Service Provider to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's website (noted above). The products and models allowed to be serviced are to be listed on the company's website. The ABS office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors, etc.



---

Ernesto Guerra, Surveyor



Certificate Number **17-BL3355922-C**  
Effective Date **07-JUL-2017**  
Expiry Date **07-JUL-2020**  
ABS Port Office **BALBOA PORT**  
Specialist's Website **www.seminsa.com.pa**

---

## CERTIFICATE OF Recognized External Specialist

This is to certify that

**Servicios Maritimos e Inspecciones, S.A. (SEMINSA)**

located at

**Colon Maritime Investor Export Processing Zone (347) Central Avenue**

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

**Inflatable Liferrafts, Inflatable Lifejackets, Hydrostatic Release Units,  
Inflatable Rescue Boats and Marine Evacuation Systems**

It is the responsibility of the Service Provider to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's website (noted above). The products and models allowed to be serviced are to be listed on the company's website. The ABS office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors, etc.



Ernesto Guerra, Surveyor